

Top down view – this is near the upper level door



The following three pictures have measurements.









Hopefully you can see the arc shaped crack from here to here



This is a crack near the coatroom and pod 6 (depending on cost we can fix it too)







and then there are 2 in the elevator



